

Deviations

§60.5420(b)(2-4)(ii); (5-6)(iii) and §60.5420a(b)(2-4)(ii); (5-6)(iii)

Facility	Legal Entity	Equipment Name	Explanation
Blue Moon Compressor Station	EQM Poseidon Midstream	Collection of fugitive emission components	Missing records of ambient temperature, sky conditions, and maximum wind conditions for survey conducted on 4/22/19. Weather conditions recorded from another survey on the same day and at an immediately adjacent facility were reported in this report as these are representative of the conditions at the time of survey.
Blue Moon Compressor Station	EQM Poseidon Midstream	One (1) Fuel Line - Braided fuel line 2"	Component found leaking on 8/10/18 was repaired on 8/16/2018 (confirmed with bubble test). Resurvey was completed on 9/24/2018 (> 30 days from repair).
Full Moon Compressor Station	EQM Poseidon Midstream	One (1) Unit 8 plug throw	Component found leaking on 8/10/18 was repaired on 8/15/2018 (confirmed with bubble test). Resurvey was completed on 9/24/2018 (> 30 days from repair).